



CRACKS IN GYPSUM PLASTER TO BE REPAIRED USING A NEW PROFILE TO MATCH EXISTING PLASTER.

REAPPLY GOLDLEAF TO CROSS AND ANGELS AT ALTAR.

CRESCENCE TABLE AND LIMESTONE ALTAR TO BE RESTORED BY A CONSERVATOR. SEE A-6.04 FOR CLEANING AND RESTORATION WORK.

COMMUNION RAILS TO BE RESTORED BY A CONSERVATOR. SEE A-6.04.