



**KEY**

	STUCCO SURFACE FAILURE-MR8		CLEAN BUILDING SURFACE.
	LOOSE STUCCO- SEE MR9.		REPAIR OR REPLACE WOOD.
	MISSING STUCCO - SEE MR12.		REPAIR CRACK
	<b>R</b> REPLACE SLATE		

**PRIORITIES:**  
 \*\*\* Roofing, chimneys and plant removal.  
 \*\* All walls and openings.

Revision & Submissions	Date

Condition Assessment  
**Greenwood Gardens**  
 774 Old Short Hills Road  
 Short Hills, New Jersey

1926 Cottage (North)

ANNABELLE BACCIFFRENNER R.A., N.J.P.A.#13776  
 MICHAEL CALAFATE R.A., N.J.P.A.#0929

**Historic Building Architects, LLC**  
 312 West State Street, Trenton, NJ 08618 Tel 609 383 3999 Fax 609 393 4333  
 Certificate of Authorization # A.C245 Expires 01/31/2006

Date: 9/20/2005

Drawn by: MH/SN

Scale: NTS

A-4.14